



FRYLANDS WOOD SCOUT OUTDOOR CENTRE

Building Risk Assessment – Pembroke 2

The Risk Assessments contained here are additional items specific to the buildings listed and should be read in conjunction with the 'All Buildings' Risk Assessment.

Facility: All Buildings		Date of Assessment: December 2016			Review Date: As required			
Assessors Name: M. Thomson		Assessor's Signature:			Date Signed:			
Facility/Hazard	Who is at risk	Before Control Measures			Existing Control Measures	After Control Measures		
		Likelihood 1-3	Severity 1-4	Risk Rating		Likelihood 1-3	Severity 1-4	Risk Rating
Kitchen Areas	Anyone using / visiting the facility	1	3	3	<ul style="list-style-type: none"> The kitchen units should be of suitable construction and finished edges suitable to minimise injury from accidental contact. E.g. children knocking into the edges / corners 	1	3	3
Sleeping Rooms – Bunk Beds	Anyone using / visiting the facility	1	2	2	<ul style="list-style-type: none"> Ensure the beds are of appropriate construction, designed for the purpose and in a good state of repair. Ensure the mattresses provided are of constructed of appropriate materials to meet the current legislation for use 	1	2	2
Furniture – failure. <i>e.g. chair collapse</i>	Anyone using / visiting the facility	1	2	2	<ul style="list-style-type: none"> Ensure the furniture is of appropriate construction, designed for the purpose and in a good state of repair. 	1	2	2

All the items below were considered in this checklist and weren't considered a risk at the time of the assessment:

Plant and Machinery

Falls from Height

Food Hygiene

Display Screen Equipment